COMMONWEALTH OF MASSACHUSETTS



THE GENERAL COURT

STATE HOUSE, BOSTON 02133-1053

January 9, 2018

Jonathan Gulliver, Highway Administrator Massachusetts Department of Transportation 10 Park Plaza, Suite 4160 Boston, MA 02116

Dear Mr. Gulliver:

We are writing to express our strong support for the application submitted by the Town of Leicester for funding through the Municipal Small Bridge Program to repair or replace the Church Street Bridge (No. L-06-011). It is our sincere hope that the Massachusetts Department of Transportation (MassDOT) will prioritize this application which seeks to address a critical infrastructure problem within the Leicester community.

A bridge closure recommendation was issued by MassDOT for the Church Street Bridge on July 31, 2017 because of multiple cracks in the stone masonry slabs supporting the roadway. We have enclosed a copy of the Inspection Report for your review.

It is our understanding that MassDOT is currently evaluating a prior Municipal Small Bridge Program grant application from the Town of Leicester for replacing the Auburn Street Bridge. However, the Town is now seeking to prioritize the Church Street Bridge project over the previous application because of the serious deficiencies with the condition of the Church Street Bridge. Moreover, the bridge closure would result in a traffic detour which spans several miles.

To that end, we would appreciate your careful consideration of the Church Street Bridge as a funding priority during the current round of funding through the Municipal Small Bridge Program. We would also appreciate MassDOT's assistance with interim measures to help the Town maintain bridge usage until comprehensive repairs or a replacement is possible.

Thank you for your time and attention to this request. If you have any further questions, or if there is any additional information we can provide in support of the Church Street Bridge project, please do not hesitate to contact either of our offices.

Sincerely,

MICHAEL O. MOORE

State Senator

Second Worcester District

KATE D. CAMPANALE

State Representative

Seventeenth Worcester District

Kate D. Camponele

Enclosure

CC: Leicester Board of Selectmen

David Genereux, Leicester Town Administrator (via email)

Barry Lorion, District 3 Acting Highway Director, MassDOT (via email)

Donny Dailey, Government and Public Affairs, MassDOT (via email)

Town of Leicester Bridge Evaluation:

Church Street over Kettle Brook

Preliminary

7/31/2017

Preliminary Cost Estimate

Scope of Work:

Rehabilitate structure

Construction Costs


Items/ Description	Unit		Unit Cost	Quantity		Item Cost
Demolition (remove existing superstructure)	LS	\$	31,800	1	\$	31,800.00
Bridge Excavation	CY	\$	80	60	Š	4,800.00
Gravel Borrow for Backfilling Structures	CY	\$	80	20	Š	1,600.00
Highway Guardrail (including bridge railing)	LF	\$	100	100	Š	10,000.00
Highway Guardrail Terminals	EA	\$	2,000	4	Š	8,000.00
4000 psi Concrete (bridge slab)	CY	\$	2,500	20	\$	50,000.00
Asphalt overlay	TON	\$	300	9	Š	2,700.00
Erosion Control	FT	\$	20	120	Ś	2,400.00
Masonry (repair/construct wingwalls)	SF	\$	150	270	Š	40,500.00
Masonry (repair abutment)	LS	\$	8,000	1	Š	8,000.00
Signing and Pavement Markings	LS	\$	4,000	1	Š	4,000.00
Repointing	LF	\$	50	167	\$	8,347.50
Temporary Shoring	LS	\$	20,000	1	Š	20,000.00
Mobilization	LS	\$	20,000	1	Š	20,000.00
Control of Water (wingwall construction)	LS	\$	40,000	1	\$	40,000.00
			Subtotal:		\$	252,147.50
			Contigency:	25%	\$	63,036.88
Design Services	Estin	nated	Construction Cost		\$	315,184.38
_			/Highway Design:		\$	95,000.00
Construction Phase Services (Inspection	, Shop Dwg	Revie	w, Rating Report)		\$	28,000.00
			Survey:		\$	6,000.00
			Permitting:		\$	8,000.00
			Hydraulic Report		\$	16,000.00
Miscellaneous			Subtotal:		\$	153,000.00
	Traffic N	Manag	ement and Police	5%	\$	15,759.22
Ut	ility Tempor	ary Si	upport/Relocation	7%	\$	22,062.91
			Subtotal:		\$	37,822.13
			Project Total:		\$	506,006.50
			Total Conceptua	l Estimate	e \$	507,000.00

Additional Details on above items:

Design fee estimated based on percentage of construction cost. Assumes all work can be performed within the right-of-way. A contingency of 25% for unknowns has been provided.

Further design is needed and this estimate has been prepared for programming purposes. Assumes \$7,500 for Post Construction Load-Rating under Construction Phase Services

Prepared by: ATB/RWP Reviewed by: JJB





Town of Leicester OFFICE OF THE TOWN ADMINISTRATOR

Town Hall, 3 Washburn Square Leicester, Massachusetts 01524-1333 Phone: (508) 892-7000 Fax: (508) 892-7070 www.leicesterma.org

August 15, 2017

Mr. Barry Lorion
District 3 Acting District Highway Director
403 Belmont Street
Worcester MA 01604

Subject: Small Bridge Program (SBP)

Dear Mr. Lorion:

The Town of Leicester is in receipt of a MassDot bridge inspection field report on the Church Street bridge over Kettle Brook. The deficiencies cited in said report prompted a July 26, 2017 recommendation from D3 Bridge Engineer Mohammed Nabulsi to close the bridge. We are evaluating that and other short-term options at this time. Our long-term objective is to repair or replace the structure with SBP assistance.

MassDot is currently evaluating a prior SBP grant application from the Town for replacing the Auburn Street bridge. We now ask that MassDot prioritize the Church Street bridge ahead of the Auburn Street request in the current round of funding.

Thank you for your attention to this request.

(mull


Sincerely.

James P. Purcell

Interim Town Administrator

Cc: Board of Selectmen

Tom Wood, Highway Supervisor





CERTIFIED MAIL RETURN RECEIPT REQUESTED

July 31, 2017

Town of Leicester Town Administrator 3 Washburn Sq. Leicester, MA 01524

Attn: Thomas Wood, Highway Supt.

SUBJECT:

NATIONAL BRIDGE INSPECTION STANDARDS (NBIS)

BRIDGE CLOSURE

Leicester: CHURCH ST / KETTLE BROOK

Bridge No: L-06-011

BIN No: 6R2

Structure No: L06011-6R2-MUN-BRI

Dear Select Board:

The Massachusetts Department of Transportation (MassDOT) - Highway Division has undertaken the inventory, inspection, and rating of locally-owned bridges to assist the cities and towns in complying with State and Federal Legislation.

The above bridge was inspected on May 21, 2017 and on July 19, 2017 and it is recommended that the bridge be CLOSED to vehicular traffic.

The reason for this recommendation is due to the multiple cracked stone masonry slabs supporting the roadway.

This letter confirms the notification to closed the bridge per a telephone conversation on July 21, 2017 between Mohammed Nabulsi, MassDOT District3 Bridge Engineer, and Thomas P. Wood, Town Superintendent of the Town of Leicester.

Your immediate action is requested. Please respond in writing confirming your action not later than August 31. 2017.

A copy of the Inspection Report regarding this recommendation is enclosed. Jonathan L. Gulliver, the District Highway Director, will be pleased to review the report with you and advise you of any programs available regarding this bridge.

Thank you for your cooperation.

Sincerely,

Patricia A. Leavenworth, P.E.

Chief Engineer

GK/gk

cc: DHD, D-3 & DBIE, D-3

Duplicate sent by Regular First Class Mail

2-DIST B.I.N. STRUCTURES INSPECTION FIELD REPORT											BR. DEPT. NO.			
03 6R2 SPECIAL MEMBER INSPECTION												3-011		
CITY/TOWN	STRUCTURE NO.	RUCTURE NO.			90-ROU	TINE IN	SP. DATE	93*-51	PEC. ME	MB. IN	isp. Dat			
LEICESTER			L06011-6R2-I		000.692		Nov 21, 20			016 May 21				
07-FACILITY CARRIED HWY CHURCH ST	MEMORIAL NAM	E/LOCAL NAME		27-YR BUILT 106-YR 1		000	•YR REHABD (NON 0000		1 106)					
06-PEATURES INTERSECTED WATER KETTLE BROC	Urban Loca		DIST, B	ŘIDGE IN	INBER	M. Azi	zi							
45-STRUCTURE TYPE 801 : Masonry Slab	-		22-OWNER Town Agency	22-OWNER 21-MAINTAINER TEAM LEADER D. Smith Town Agency Town Agency										
107-DECK TYPE 9: Other	WEATHER Cloudy													
	Not App	olicable	X	A	bridge		Advan	Advance PLANS (Y/N): N						
Actual Posting N		N N	(Y=Yes.N	Signs in Place (Y=Yes,N=No, NR=Not Required)										
Recommended Posting N N N N Legibility/ Walved Date: 00/00/0000 EJDMT Date: 00/00/0000										(V.C.R.) (Y/N): N				
RATING														
Rating Report (Y/N): N Date: Request for Rating or Rerating (Y/N): Y HIGH(X) MEDIUM() LOW()														
REASON: Never rated, Condition of slab. Inspection data at time of existing rating 158: - 159: - 160: - 162: - Date:00/00/0000														
SPECIAL MEMBER(S):														
MEMBER	CRACK (Y/N):	WELD'S CONDITION (0-6)	LOCATION OF COR COLLISION DAMA	ROSION, SECTION : GE, STRESS CONC	N LOSS (%), CRACKS, CONDITION FRENCH PREVIOUS PREPRIOR (0-9) (0-9)					ATING OF MEMBER I RATING ANALYSIS 3 352			ciencies	
A Item 58.2 - Deck Condition	N	N	See Item 59.	•	3	3	No	t Raf	ed		S-A			
B Item 59.15 - Masonry Slab	N	N	See remarks	in comme	nts se	ction.	3	3	No	t Raf	ed		S-A	
С														
D	· -			·										
E														
List of field tests performed:		<u></u>	<u> </u>					·	Į-	58 I	-59	I-60	I-62	
None	(Ov	(Overall Previous Condition)						3	5					
	(Ove	(Overall Current Condition) 3 3 5								-				
DEFICIENCY: A defect in a stru		equires correct	ve action.											
CATEGORIES OF DEFICIENCE M= Minor Deficiency - Deficiencies	rich are atio	or in nature, gene	raily do not impact the structure	al Integrity of the bridge a	nd could easily	be repaired	. Examples l	include but	ore not Seite	d to: Spelle	d concrete	, Minor po	på	
S= Severe/Major Deficiency - Deficiency	iclencies whi Iclencies whi roded rebers,	net, minor scular In are more exter Considerable set	g, Crogges cramage, etc. stre in nuisee and need more ; tisment, Considerable scoudry	planning and effort to rep g or undermissing, Modern	ek, Examples i to to extensive	nciude but a conveion to	re not limited structural of	to: Modern teal with me	te to major o neucable los	leterlaration e of section	i bi canciei , etc.	ів, Єхрозі	ons be	
C-Sim Critical Structural Deficiency. Adelicency in a structural element of a bridge that poses an extreme unselfs condition due to the feature or imminent failure of the element which will affect the element integrity of the bridge. C-His Critical Hazard Deficiency. Adelicency in a component or atment of a bridge that poses on accesses hexard or unselfs condition to the probin, but does not import the structural integrity of the bridge. Examples														
	include etc.	put are not limite	d to; Lause concrete hanging o	coun over while or pedes	erans, Ahole (, a spolewick	UNIT STRY CO	nes winues	es podestife	m' maduğ	econt of	onoga rail	ing,	
URGENCY OF REPAIR: 1 = Immediate- (Inspector(s) transactor	ely contact D	istrict firidge inep	notice Engineer (DBIE) to repo	nt the Deficiency and to m	coke further i	sstruction fro	m him/hir].	d., g						

P = Prioritize-

(Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repetre made when funds end/or manpower is evellable).

INSPECTION DATE CITY/TOWN B.I.N. BR. DEPT. NO. 8.-STRUCTURE NO. LEICESTER 6R2 L-06-011 L06011-6R2-MUN-BRI MAY 28, 2017

REMARKS

BRIDGE ORIENTATION

According to the compass the approaches are North and South and the elevations are East and West. This is a 2 span stone masonry slab bridge with 11 slabs in each span numbered West to East. The spans and both stone masonry abutments are labeled North and South. There is a stone masonry pierwall. See Sketch 1.

GENERAL REMARKS

The town of Leicester was not able to provide any plans for this bridge.

ITEM 59 - SUPERSTRUCTURE

Item 59.15 - Masonry Slab

There are many areas of missing and deteriorated pointing between slabs resulting in large gaps averaging 4 in. wide. Some gaps have minor active leakage and moderate to heavy efflorescence. See Photo 1.

South span

Slab #5: The slab has been replaced by concrete encased steel beams. The concrete encasement has longitudinal hairline cracks with heavy efflorescence, a 2 ft. long x 10 in. wide x 1-1/2 in. deep spall at the South end, a 26 in. long x 10 in. wide x 1-1/2 in. deep spall at 3 ft. from the South end and a 6 in. diameter x 3/4 in. deep spall at the North end. See Photo 2.

Slab #7: At 30 in. from the South end there is a full height x full slab width x 1 in. wide crack. The slab has collapsed down and is sagging 3 in. below the the adjacent slabs. Between slabs #7 and #8 there is a full length x 10 in. wide x full depth gap with a 2 ft. long x 8 in. deep void above the crack. See Photo 3. The wearing surface shows no settlement above this area.

Slab #9: There are timber boards across the full span that are assumed to be falsework for concrete. See Photo 4.

Slab #10: At the South end there is a 2 ft. long x full width x 3 in. thick delaminated section of stone. The delamination has separated 2 in. from the slab above and has a full width x 1/2 in. wide crack. See Photo 5.

Slab #11: At 2 ft. from the South end there is a full slab width x 0.04 in. wide crack that extends 6-1/2 in. up the fascia side of the slab. At 3 ft. from the pier there is a full slab width x 0.04 in. wide x full height crack with adjacent delaminated and chipped stone. See Photo 6.

Sketch / Photo Log

Sketch 1: Framing plan.

Photo 1: West side of South span. Photo 2: Slab #5 in South span. Slab #7 in South span. Photo 3: Photo 4: Slab #9 in South span. Slab #10 in South span. Photo 5: Slab #11 in South span.

Photo 6:

PAGE 3 OF

TY/TOWN ICESTER			I.N. R2		. dept, no. 06-011					UCTUR 11-6R2	BNO. 2-MUN-BI	રા		CTION DATE MAY 28, 2017
						SKE	ТСНІ	S				•		
NORTH ABUTMENT	2'-0"#	1-1-	15	15**	7-0'±	₹-		-7'*	37.	2'-1"4	2'-10"#	2'-2"#	, , , , , , , , , , , , , , , , , , ,	
PICE (HORTH FACE)	E12	313	\$14	S16	514	\$1	7	\$10	SIE	920	\$ 31	\$23	EVER HINCH	
par (south fact)—					<u> </u>				- -					
	\$ 1	92	5 5	*	25	54	s7	20		59	\$10	\$11	\$20.00 WWW	
SOUTH ABUTHERT						-			- -					
	7-0°±	17'4	22"±	2-5±	2'-5'4	17°±	2'-2'à	5,-0,7	1	<u>-72 </u>	F-F4	Z-1'±		
							6'-6'2				··· .		ļ	
MOTES: 1. ORGAN, OF 2. SKITCHES O 3. ALL DRESHS 4. SUPPLEMENT FOR MAR ALL DRESHS COMPONENTS COMPONENTS							ING PLA	N				D CONCRETE E WASONAL BOY WASONAL BOY WASON	IOS HCASEMENT	
S	ketch	1:	Fram	ing plar	1.									

| B.I.N. | BR. DEPT. NO. | 8.-STRUCTURE NO. | INSPECTION DATE | Leicester | L-06-011 | L06011-6R2-MUN-BRI | MAY 28, 2017

PHOTOS



Photo 1: West side of South span.




Photo 2: Slab #5 in South span.

| B.I.N. | BR. DEPT. NO. | 8.-STRUCTURE NO. | INSPECTION DATE | Leicester | L-06-011 | L06011-6R2-MUN-BRI | MAY 28, 2017

PHOTOS




Photo 3: Slab #7 in South span.



Photo 4: Slab #9 in South span.

PHOTOS



Photo 5: Slab #10 in South span.




Photo 6: Slab #11 in South span.